








Measuring for Body Armour

					
Size	Chest	Front Length	Back Length	Mid Ab	Waist
Small	34-38	13	17	28	28
Medium	38-43	14	18	32	32
Large	43-46	15	19	36	36
XL	46-48	16	20	40	40
XXL	48-49	16.5	20.5	44	44
XXXL	50-51	17	21	47.5	47.5
XXXXL	52-53	17.5	21.5	51.5	51.5

Measuring for Helmet

		For accurate head measure, place a tape measure across the forehead and measure around the full circumference of the head. Keep the tape snug for accurate results.		
Size	Minimum head Size		Maximum head Size	
Small	52 cm	20.5 in	54 cm	21.2 in
Medium	54 cm	21.2 in	59 cm	23.2 in
Large	57 cm	22.5 in	63 cm	24.8 in
XLarge	63 cm	24.8 in	64cm	25.2 in

Measuring for Protective Gloves

		Extend hand flat. With a tailor's measuring tape, wrap around strongest hand below the knuckles, but above thumb. Make a loose fist. Round the measurement up to the nearest inch for your approximate glove size.			
Size	Centimetres	Inches	Size	Centimetres	Inches
Small	20.3 cm	8 in	XL	27.9cm	11 in
Medium	22.9 cm	9 in	XXL	30.5 cm	12 in
Large	25.4 cm	10 in			